



Carlisle Machine Works Inc.

AMERICAN MADE SINCE 1918



INCORRECT CANDLE LENGTH. NOTE
TUBES AND CENTERFIRE TURNING RED.
INCREASE GAS AND OXY ON VALVES TILL
COLOR RETURNS TO NORMAL.



CORRECT CANDLE LENGTH. NOTE
TUBES AND CENTERFIRE NORMAL
COLOR. CANDLES SHOULD NEVER BE
SMALLER THEN 3/8".



DAMAGE DUE TO EXCESSIVE BURNING OF CANDLES UNDER 3/8". CONTACT A CARLISLE
TECHNICIAN IMMEDIATELY FOR REFURBISHING/REPAIR OF YOUR TORCH. 800-922-1167.